



LAWRENCE
LIVERMORE
NATIONAL
LABORATORY

Structure and Phase Transformations in Pu Alloys

A. J. Schwartz, T. B. Massalski, H. Cynn, W. J. Evans,
D. L. Farber, M. A. Wall, K. J. M. Blobaum, K. T. Moore,
J. R. Jeffries

March 19, 2008

2008 MRS Spring Meeting
San Francisco, CA, United States
March 24, 2008 through March 28, 2008

Disclaimer

This document was prepared as an account of work sponsored by an agency of the United States government. Neither the United States government nor Lawrence Livermore National Security, LLC, nor any of their employees makes any warranty, expressed or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States government or Lawrence Livermore National Security, LLC. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States government or Lawrence Livermore National Security, LLC, and shall not be used for advertising or product endorsement purposes.

Lawrence Livermore National Laboratory

Structure and Phase Transformations in Pu Alloys

2008 Materials Research Society Spring Meeting
March 25, 2008
San Francisco, CA



A.J. Schwartz, T.B. Massalski*, H. Cynn, W.J. Evans, D.L. Farber,
M.A. Wall, K.J.M. Blobaum, K.T. Moore, and J.R. Jeffries


*Carnegie Mellon University

Lawrence Livermore National Laboratory, P. O. Box 808, Livermore, CA 94551
This work performed under the auspices of the U.S. Department of Energy by
Lawrence Livermore National Laboratory under Contract DE-AC52-07NA27344

LLNL-CONF-xxxxxx

We shall focus in this review on the materials science aspects of Pu and Pu-based alloys



■ The usual connections are as follows:

- 
- **Free energy and thermodynamics**
 - **Phase diagrams**
 - **Transformations (nucleation and growth)**
 - **Isothermal martensitic phase transformations**
 - **Pressure-induced phase transformations**
 - **Microstructure**
 - **Properties**



Self-irradiation

Self-irradiation damage is the primary source of microstructural change with age





Through focus transmission electron microscopy images of a 42-year-old Pu-Ga alloy




Allotropic phase transformations


Plutonium undergoes five solid-solid allotropic phase transformations between the ground state and the liquid




10%




3.5%




7%



-0.5%




-3%



Liquid (640°C +)
ρ = 16.5 g/cm³

Equilibrium phase diagram

For decades, the “West” accepted that the δ phase was thermodynamically stable at ambient conditions



Ellinger, Land, and Struebing, J. Nuc. Mat. (1964)

Hecker and Timofeeva, LA Science (2000)

**The δ -phase retained to room temperature is metastable
Timofeeva (2003) estimated 10,000 years to decompose**

Chebotarev, Plutonium and Other Actinides 1975 (1975)

Adler, Met Trans (1991)


Timofeeva, Aging Studies and Lifetime Extension of Materials (2003)




Low-temperature $\delta \rightarrow \alpha'$ martensitic transformation

Upon cooling to sub-ambient temperatures, δ transforms to α' via an isothermal martensitic transformation

The $\delta \rightarrow \alpha'$ isothermal martensitic transformation can be induced with continuous cooling experiments



Pu - 2.0 at.% Ga
-155°C, 4 hours
Optical micrograph



Wall et al. LLNL (2008)


**Partially transformed
($\delta + \alpha'$ phases)**

Like the δ -phase at room temperature, α' is also metastable


Low-temperature $\delta \rightarrow \alpha'$ martensitic transformation

The α' particles that form from the isothermal martensitic transformation appear as lathes in optical microscopy

The martensite start temperature, M_s , and martensite reversion temperature, R_s , are a function of Ga content



Double-C plots of a Pu - 1.9 at.% Ga alloy





Orme *et al.* Pu & Other Actinides (1975)

The $\delta \rightarrow \alpha'$ isothermal martensitic transformation goes to ~ 25% completion



Low-temperature $\delta \rightarrow \alpha'$ martensitic transformation

$\alpha' \rightarrow \delta$ reversion has been shown to be via a avalanche martensitic mode in both dilatometry and DSC



Blobaum et al. Met Trans (2005)

Differential scanning calorimetry of the $\alpha' \rightarrow \delta$ reversion shows periodic spikes

Dilatometry traces through the $\alpha' \rightarrow \delta$ reversion exhibit steps


The derivative (dL/dt) reveals periodic spikes

Lawrence Livermore National Laboratory




Low-temperature $\delta \rightarrow \alpha'$ martensitic transformation

The amount of the $\delta \rightarrow \alpha'$ transformation is dependent on details of the thermal cycling and “conditioning”



The amount of transformation in Pu - 1.8 and 2.0 at.% Ga alloys decrease with each thermal cycle




- Conditioning times of ~6 hours are required for reproducible amounts of transformation
- α_m embryos may be forming as a precursor to the $\delta \rightarrow \alpha + \text{Pu}_3\text{Ga}$
- These α_m embryos initiate α' on subsequent cooling




Pressure-induced $\delta \rightarrow \alpha'$ martensitic transformation

The $\delta \rightarrow \alpha'$ transformation can also be induced by pressure



- Under pressure, Pu - Ga alloys transform directly to α' and undergo either a direct ($\alpha' \rightarrow \delta$) or indirect ($\alpha' \rightarrow \beta' + \delta \rightarrow \gamma' + \delta \rightarrow \delta$) reversion
- Reversion characteristics are similar to those in thermally-induced transformations




Pu - 2 at.% Al alloys transform first to β' then to α' under pressure


Why do Pu-Al alloys transform through β' whereas Pu-Ga alloys transform directly to α' ?

Pressure-induced $\delta \rightarrow \alpha'$ martensitic transformation



Diamond anvil cell experiments on a Pu - 2 at.% Ga alloy reveal $\delta \rightarrow \gamma' \rightarrow \alpha'$ transformation sequence



Faure et al. MRS Proceedings (2006)



In the DAC, Pu - 2 at. Ga transforms through the sequence $\delta \rightarrow \gamma' \rightarrow \alpha'$





Sadigh and Wolfer, PRB (2005)



Pressure-induced $\delta \rightarrow \alpha'$ martensitic transformation

Recent experiments at LLNL also suggest intermediate transitions between δ and α'




- Diffraction peaks of the δ phase split at low pressures to a γ like structure
- γ like structure structure appears at ~0.6 GPa

- γ like structure structure disappears at ~1.6 GPa

At low pressure, δ phase distorts to δ'

- Small amounts (<~1%) of γ and α' coexist with δ at ambient
- Is identified at ~0.1 GPA
 - I4/mmm (S.G. 139, $z = 2$)
 - $a = 3.240\text{\AA}$
 - $c = 4.617\text{\AA}$
 - $V = 48.47\text{\AA}^3$ (0.2% denser than δ -Pu)
 - Pressure induces growth of γ and α'



Pressure-induced $\delta \rightarrow \alpha'$ martensitic transformation

Upon cooling, Harbur reported that a 0.68 at.% Ga alloy has a density intermediate between δ and α phases

Harbur, JALCOM (2007)

QuickTime™ and a compressed) decompressor needed to see this picture.

After compressing to 1 GPa

Alloy	% α'	% δ	% amorphous
1.0 at.% Ga	87	0	13
1.7 at.% Ga	66	0	34
2.5 at.% Ga	68	12	20

Harbur, JALCOM (2007)



Harbur proposes that the δ phase transforms to $\alpha' +$ amorphous phase

- on cooling low solute alloys
- under pressure



Pressure-induced $\delta \rightarrow \alpha'$ martensitic transformation

We are coupling low pressure recovery experiments with TEM to elucidate the mechanism and morphology




2.3 mm diameter specimens are slowly compressed to 1 GPa in the large volume moissanite anvil cell




Pressure-induced $\delta \rightarrow \alpha'$ martensitic transformation

Optical microscopy and x-ray diffraction of the compressed specimen reveals α' and δ phases






Optical microscopy does not have the resolution to differentiate between phases



Our X-ray diffraction does not indicate the presence of an amorphous phase

Pressure-induced $\delta \rightarrow \alpha'$ martensitic transformation

Preliminary TEM reveals fine-grained α' and small amounts of δ – no evidence of an amorphous phase



Pressure-induced $\delta \rightarrow \alpha'$ transformation

Average α' grain size ~ 100 s nm

Implies nucleation dominated mechanism

δ phase is observed dispersed between the α' grains

High dislocation density

No apparent orientation relationship (yet)

Summary

- Low temperature isothermal $\delta \rightarrow \alpha'$ transformation
 - Nucleation and growth are limited
 - Large lath-shaped particles form
 - Intermediate phases are possible
- Pressure-induced $\delta \rightarrow \alpha'$ transformation
 - Nucleation dominates
 - Very fine grain size results
 - No evidence of the amorphous phase
 - Intermediate phases exist

